

## Adaptador Macho GHT

### Macho GHT x Macho NPTF



GHT	NPTF	Latón # de Parte	Latón Libre de Plomo <sup>3</sup> # de Parte	Rosca Macho	Acero Inox. 303 # de Parte
3/4"	3/8"	5081206C <sup>1</sup>	---	---	---
3/4"	1/2"	5081208C <sup>1</sup>	5081208CLF	NPT	5081208SS
3/4"	3/4"	5081212C <sup>1</sup>	---	NPT	5081212SS
3/4"	3/4" x 1/2"	5141212C <sup>1,2</sup>	5141212CLF <sup>2</sup>	NPT	5141212SS <sup>2</sup>
3/4"	1"	5081216C <sup>1</sup>	---	---	---

<sup>1</sup> Macho GHT extendido, rosca profunda.

<sup>2</sup> Tiene hembra NPT 1/2" en el D.I. del lado NPT macho 3/4".

<sup>3</sup> Latón libre de plomo <=0.25% plomo; aleación CA2745; aleación C46400.

### Rosca Macho



Macho x Macho	Latón # de Parte	Acero Inox. 303 # de Parte
GHT x GHT	5091212C	5091212SS
1" NPSH x GHT	5091612C <sup>2</sup>	---

<sup>1</sup> Macho GHT extendido, rosca profunda.

<sup>2</sup> Rosca NPSH.

### Macho GHT x Hembra NPTF



Macho GHT	Hembra NPTF	Latón # de Parte	Latón Libre de Plomo # de Parte
3/4"	1/4"	5071204C	---
3/4"	3/8"	5071206C	---
3/4"	1/2"	5071208C	---
3/4"	3/4"	5071212C	5071212CLF <sup>1,2</sup>

Macho GHT	Hembra NPT	Acero Inoxidable 303 # de Parte
3/4"	1/2"	5071208SS
3/4"	3/4"	5071212SS

<sup>1</sup> Rosca NPT.

<sup>2</sup> Latón libre de plomo <=0.25% plomo, aleación CA2745; aleación C46400.

### Macho x Macho x Tubería Hembra



Macho GHT x Macho GHT x Hembra NPT	Latón libre de Plomo # de Parte
3/4" x 3/4" x 1/2"	5091212CLF